

Work Order ID 62027

Wednesday, September 15, 2010 9:11:28 AM



Page 1

Item ID: D206-559-011

Accept



Setup Start



Revision ID:

Item Name: Bearpaw

Stop



Start Date: 9/15/2010 Start Qty: 4.00



Cust Item ID:

Required Date: 9/16/2010 Req'd Qty: 4.00



Customer:

Reference: ECN 10-613

Approvals:

Process Plan: MX

Date: 10-9-15

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

IIN-D206-559

J -PRELIM

200

0.00



Packaging

Memo

0.00

PULL FROM STOCK D206-559-011

B 58476 X 4

REMOVE AN4-15A BLOTS AND REPLACE WITH AN4-20A

MEL WILL MAKE AN ADJ

ADD DSI TO KITS IN STOCK

UPDATE LABELS AND PAPERWORK TO CHANGE 7

210

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

8/10/09/16

10/9/16 SL

740

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 62027

Wednesday, September 15, 2010 9:11:28 AM



Page 2

Item ID: D206-559-011

Accept



Setup Start



Revision ID:

Stop



Item Name: Bearpaw

Start Date: 9/15/2010 Start Qty: 4.00



Cust Item ID:

Required Date: 9/16/2010 Req'd Qty: 4.00



Customer:

Reference: ECN 10-613

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

215



Packaging

Identify as per dwg & Stock Location: 11

0.00

Revc

10/9/16 40 SP

Memo

0.00

Packaging

ID AND STOCK UNDER NEW BATCH NUMBER

220



QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/09/17

ME 10-9-16

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, September 15, 2010 8:58:58 AM

Page 1

Work Order ID: 62027

Parent Item: D206-559-011

Parent Item Name: Bearpaw



Start Date: 9/15/2010

Required Date: 9/16/2010

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP Rev:C 04.02.17 Blank size changed KJ/JLM
 IPP Rev:D 07-01-02 Was K10007 JLM
 IPP Rev:E 08-05-05 up a chg DD verified by:EC
 IPP Rev:F 08-10-15 New Manufacturing Method JLM Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

AN4-15A		Purchased	No				Each	323.0000	8	-32			
Bolt													

Location	Loc Qty	Loc Code
ST338	112	
ST358	211	
112905	12	
114784	21	
115108	78	
115371	100	

M114292 10/9/10

AN4-20A		Purchased	No				Each	678.0000	32				
Bolt													

Location	Loc Qty	Loc Code
ST359	678	
104016	662	
16895	16	

32 10/9/10

D206-559-011		Manufactured	No				Each	8.0000	4				
Bearpaw													

Location	Loc Qty	Loc Code
FG011	8	
52523	4	
58476	4	

4 10/9/10 SL 40

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

REFERENCE ONLY

5.0 PARTS LIST (D206-559 REV. K)
32.7 PARTS LIST (ICA-D205-559 REV. 2)






Qty -011	Qty -013	Qty -021	Qty -023	Qty -031	Qty -033	Qty -113	Part Number	Description
X							D206-559-011	Bearpaw Kit 206 A/B
	X						D206-559-013	Bearpaw Kit 206 L/L1/L3/L4/407
		X					D206-559-021	Narrow Bearpaw Kit 206 A/B
			X				D206-559-023	Narrow Bearpaw Kit 206 L/L1/L3/L4/407
				X			D206-559-031	Wearplate Kit
					X		D206-559-033	Wearplate Kit
						X	D407-559-113	Large Bearpaw Kit 206 L/L1/L3/L4/407
4	6	4	6				D2182B050	RUBBER CUSHION
8	12	8	12			20	D2274	RADIUS BLOCK
2							D2435	19" X 16" BEARPAW
	2						D2432F	19" X 24" BEARPAW
		2					D2671	13" X 16" BEARPAW
			2				D2672F	13" X 24" BEARPAW
4	6	4	6				D2438	CLAMP
8	12	8	12				D2529	WASHER
	6		6				D2732-050	RUBBER CUSHION
						2	D3456-1	WASHER
					2		D3859-041	WEARPLATE
				2			D3860-041	WEARPLATE
						2	D4010-041	BEARPAW ASSEMBLY
						8	D4011-1	CLAMP, SHORT
						2	D4011-3	CLAMP, LONG
						8	D4011-5	CLAMP, SHORT (OEM)
						10	D4012-1	CUSHION
						2	AN4C10A	BOLT
8	12	8	12	8	12		AN4-17A	BOLT
8	12	8	12	8	12		AN4-20A	BOLT (WAS AN4-15A)
						4	AN4C13A	BOLT
						8	AN4C15A	BOLT
						8	AN4C17A	BOLT
16	24	16	24				AN960JD416	WASHER (OR NAS1149D0463J)
8	12	8	12	8	12		MS21042L4	NUT (OR MS21042-4)
						20	MS21043-4	NUT
				8	12		NAS1149D0463J	WASHER (OR AN960JD416)
2		2					QS200M44S	CLAMP

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: 
D. SHEPHERD (DE # 02)

DATE: 10.06.30
CERT. NO.: SH92-17
ISSUE NO.: 7

DESIGN		DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN			
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9527	SHEET 2 OF 2
APPROVED		TITLE	SCALE
DE APPR.		BOLT CHANGE	NTS
DATE	10.06.30	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	